

The recall involves the following catalog or part numbers:

CQO116L100PGRB	QO130M200PRB	QOC30UFWG
CQO116M100PRB	QO140L200PGRB	QOC30UFWGW
CQO116M60PRB	QO140M200PRB	QOC30US
CQO124L125PGRB	QO142L225PGRB	QOC32UF
CQO124M100PRB	QO142M200PRB	QOC32UFW
CQO140L200PGRB	QO142M225PRB	QOC40UF
CQO140M200PRB	QO1816M200PFTRB	QOC40UFW
NQC20FWG	QO816L100PRB	QOC40US
NQC20FWGW	QOC12UF	QOC42UF
NQC30FWG	QOC12US	QOC42UFW
NQC30FWGW	QOC16UF	QOC42US
QO112L125PGRB	QOC16UFW	QOC54UF
QO112L200PGRB	QOC16US	QOC54UFW
QO112M100PRB	QOC20U100F	QOC60UF
QO116L125PGRB	QOC20U100FW	QOCMF30UC
QO116M100PRB	QOC20U100S	QOCMF30UCW
QO120M100PRB	QOC20UFWG	QOCMF42UC
QO120M150PRB	QOC20UFWGW	QOCMF42UCW
QO120M200PRB	QOC24UF	QOCMF54UC
QO124L125PGRB	QOC24UFW	QOCMF54UCW
QO124M100PRB	QOC24US	QOCMF60UC
QO124M125PRB	QOC30U125C	QOCMF60UCW
QO130L200PGRB	QOC30UF	
QO130M150PRB	QOC30UFW	