



MID-ATLANTIC CONSTRUCTION SAFETY COUNCIL
Fall Protection Equipment Inspection Month
 May 2017

Fall Protection Equipment Inspection

"Trust, but verify" – Ronald Reagan



Are you using
 Fall Protection properly?

Scan the QR codes to get more information



MACSC.org



LinkedIn Group
 MACSC



OSHA.gov/stopfalls

Previous years' results	
2016:	194 Pieces of Fall Protection Equipment Removed
2015:	279 Pieces of Fall Protection Equipment Removed
2014:	498 Pieces of Fall Protection Equipment Removed
Total:	*Between 3 years, 971 lives were potentially saved

Areas to Inspect:

Harness

- Webbings
- D-rings
- Buckles
- Eyelets
- Stitching
- Load Indicator

Lanyards

- Webbing/Rope/Cable
- Snap hooks
- Shock Absorber
- Splicing/stitching

Anchorage

- Webbing
- D-rings
- Mechanical Parts
- Pins & Locking devices
- Function
- Load Indicator

Retractable/PFL/SRL

- Outer case
- Webbing/Cable
- Snap hooks
- Load indicator
- Function

Miscellaneous Equipment

